



SERVICE BULLETIN

Importance: High

**Models Affected: “The Fast and the Furious Superbikes”
Serial Numbers 4357-6007**

Raw Thrills has identified a potential issue associated with certain games manufactured in the United States. As a result, Raw Thrills is issuing an upgrade kit to prevent any problems from arising with these games. Under rare conditions, it is possible for a PCB inside the game to develop a short that could lead to extreme overheating or fire.

Continued operation of this game without performing the necessary inspection and rework may result in a eventual fire hazard.

Cause: Improper standoffs were installed on a range of our PCB's. Over-tightening during game assembly compressed these standoffs, leading to increased stress on the board and, in rare cases due to shock from transport or placement, fracture. The board fracture then introduces shorts and low-impedance circuits between 5V and GND.

Remedy: Relieve over-tightening and replace standoffs if necessary; add fuse holder (for general improved protection against over-current situations).

**For Additional Assistance Please Contact Brady Distributing
at 704-357-6284**